



Chipsmall Limited consists of a professional team with an average of over 10 year of expertise in the distribution of electronic components. Based in Hongkong, we have already established firm and mutual-benefit business relationships with customers from,Europe,America and south Asia,supplying obsolete and hard-to-find components to meet their specific needs.

With the principle of “Quality Parts,Customers Priority,Honest Operation,and Considerate Service”,our business mainly focus on the distribution of electronic components. Line cards we deal with include Microchip,ALPS,ROHM,Xilinx,Pulse,ON,Everlight and Freescale. Main products comprise IC,Modules,Potentiometer,IC Socket,Relay,Connector.Our parts cover such applications as commercial,industrial, and automotives areas.

We are looking forward to setting up business relationship with you and hope to provide you with the best service and solution. Let us make a better world for our industry!



## Contact us

Tel: +86-755-8981 8866 Fax: +86-755-8427 6832

Email & Skype: info@chipsmall.com Web: www.chipsmall.com

Address: A1208, Overseas Decoration Building, #122 Zhenhua RD., Futian, Shenzhen, China





**100**

---

**EZ Digital  
Multimeter  
Instruction Manual**

# SAFETY CONSIDERATIONS

***WARNING: Please follow manufacturers test procedures whenever possible. Do not attempt to measure unknown voltages or components until a complete understanding of the circuit is obtained.***

## GENERAL GUIDELINES

### **ALWAYS**

- Test the 100 before using it to make sure it is operating properly.
- Inspect the test leads before using to make sure there are no breaks or shorts.
- Double check all connections before testing.
- Have someone check on you periodically if working alone.
- Have a complete understanding of the circuit being measured.
- Disconnect power to circuit, then connect test leads to the 100, then to circuit being measured.

### **NEVER**

- Attempt to measure unknown high voltages.
- Connect the test leads to a live circuit before setting up the instrument.
- Touch any exposed metal part of the test lead assembly.

# CATEGORY RATINGS DEFINITIONS

## IEC 1010

### **Over Voltage:**

Cat II - 1000V

CAT III - 600V

Pollution Degree 2

**CAT II - 1000V Installation Category (Overvoltage Category) II:** Includes voltages encountered on the step down side of the transformer on the building and at a distance of 10 meters from the CAT III source.

**CAT III - 600V Installation Category (Overvoltage Category III):** Includes voltage encountered on the distribution level with short distance to the main service connection.

**Pollution Degree 2** Normally only nonconductive pollution occurs. Occasionally temporary conductivity caused by condensation must be expected.

## SPECIFICATIONS

<u>Function</u>	<u>Range</u>	<u>Resolution</u>	<u>Accuracy</u>
<b>DCV</b>	1.5V- 4V	0.001V	$\pm(0.5\% + 4)$
	40.00V	0.01V	
	400.0V	0.1V	
	600V	0.1V	$\pm(0.8\% + 4)$
<b>ACV</b>	1.7V-4V	0.001V	$\pm(0.8\% + 4)$
	40.00V	0.01V	
	400.0V	0.1V	
	600V	1V	$\pm(1.2\% + 4)$
<b>OHM</b>	400.0	0.1	$\pm(0.8\% + 4)$
	4.000k	0.001k	
	40.00k	0.01k	
	400.0k	0.1k	
	4.000M	0.001M	
	40.00M	0.01M	$\pm(2.0\% + 4)$

## GENERAL SPECIFICATIONS

Power Supply	2 Each 1.5 Volt "AA" Batteries
Battery Life	560 hrs. Alkaline
Size (H x L x W)	45mm x 78mm x 153mm (1.8" x 3.1" x 6.0")
Weight	340g (12 oz)

## MEASURING AC/DC VOLTAGE

Make sure that the ground and positive leads are plugged into the proper receptacle for corresponding function positions.



***Do not attempt to make a voltage measurement of more than 500V or of a voltage that is unknown.***

### ***Measurement Procedure:***

1. Disconnect power to circuit to be measured.
2. Plug black test lead into the **COM** input jack.
3. Plug the red test lead into the **V/Ω** input jack.
4. Set the rotary switch to the “ON” position.
5. Connect test leads to circuit to be measured.
6. Reconnect power to circuit to be measured.
7. Read the voltage on the TPI 100.

**Note: For Auto mode to operate properly, DC voltage must be between +0.7 and 600V. AC voltage must be between 3 and 500V.**

## MEASURING RESISTANCE

### **⚠ WARNING**

*Do not attempt to make resistance measurements with circuit energized. For best results, remove the resistor completely from the circuit before measuring.*

*NOTE: To make accurate low ohm measurements, short the test leads together and record the resistance reading. Deduct this value from actual readings.*

### **Measurement Procedure:**

1. Disconnect power to circuit to be measured.
2. Plug black test lead into the **COM** input jack.
3. Plug the red test lead into the **V/Ω** input jack.
4. Set the rotary switch to the "ON" position.
5. Connect test leads to circuit to be measured.
7. Read the resistance on the TPI 100.

# MAINTENANCE

1. **Battery Replacement:** The 265 will display a battery symbol when the internal 9 Volt battery needs replacement. The battery is replaced as follows:
  - a. Disconnect and remove all test leads from live circuits and from the 265.
  - b. Loosen the screw from the back of the 265 battery cover.
  - c. Remove the battery compartment cover.
  - d. Remove old battery and replace with new battery. Observe the correct polarity on the battery.
  - e. Reassemble the instrument in reverse order from above.
  
2. **Cleaning your 265:**

Use a mild detergent and slightly damp cloth to clean the surfaces of the 265.



## SAFETY CONSIDERATIONS

**WARNING:** *Please follow manufacturers test procedures whenever possible. Do not attempt to measure unknown voltages or components until a complete understanding of the circuit is obtained.*

## GENERAL GUIDELINES

### ALWAYS

- Test the 100 before using it to make sure it is operating properly.
- Inspect the test leads before using to make sure there are no breaks or shorts.
- Double check all connections before testing.
- Have someone check on you periodically if working alone.
- Have a complete understanding of the circuit being measured.
- Disconnect power to circuit, then connect test leads to the 100, then to circuit being measured.

### NEVER

- Attempt to measure unknown high voltages.
- Connect the test leads to a live circuit before setting up the instrument.
- Touch any exposed metal part of the test lead assembly.

## CATEGORY RATINGS DEFINITIONS

### IEC 1010

#### **Over Voltage:**

Cat II - 1000V

CAT III - 600V

Pollution Degree 2

**CAT II - 1000V Installation Category (Overvoltage Category) II:** Includes voltages encountered on the step down side of the transformer on the building and at a distance of 10 meters from the CAT III source.

**CAT III - 600V Installation Category (Overvoltage Category) III:** Includes voltage encountered on the distribution level with short distance to the main service connection.

**Pollution Degree 2** Normally only nonconductive pollution occurs. Occasionally temporary conductivity caused by condensation must be expected.

## SPECIFICATIONS

Function	Range	Resolution	Accuracy
<b>DCV</b>	1.5V- 4V	0.001V	±(0.5% + 4)
	40.00V	0.01V	
	400.0V	0.1V	
	600V	0.1V	
<b>ACV</b>	1.7V-4V	0.001V	±(0.8% + 4)
	40.00V	0.01V	
	400.0V	0.1V	
	600V	1V	
<b>OHM</b>	400.0	0.1	±(0.8% + 4)
	4.000k	0.001k	
	40.00k	0.01k	
	400.0k	0.1k	
	4.000M	0.001M	
	40.00M	0.01M	

## GENERAL SPECIFICATIONS

Power Supply	2 Each 1.5 Volt "AA" Batteries
Battery Life	560 hrs. Alkaline
Size (H x L x W)	45mm x 78mm x 153mm (1.8" x 3.1" x 6.0")
Weight	340g (12 oz)

## MEASURING AC/DC VOLTAGE

Make sure that the ground and positive leads are plugged into the proper receptacle for corresponding function positions.



**Do not attempt to make a voltage measurement of more than 500V or of a voltage that is unknown.**

### Measurement Procedure:

1. Disconnect power to circuit to be measured.
2. Plug black test lead into the **COM** input jack.
3. Plug the red test lead into the **V/Ω** input jack.
4. Set the rotary switch to the "ON" position.
5. Connect test leads to circuit to be measured.
6. Reconnect power to circuit to be measured.
7. Read the voltage on the TPI 100.

**Note: For Auto mode to operate properly, DC voltage must be between +0.7 and 600V. AC voltage must be between 3 and 500V.**

## MEASURING RESISTANCE

### **⚠WARNING**

*Do not attempt to make resistance measurements with circuit energized. For best results, remove the resistor completely from the circuit before measuring.*

**NOTE:** *To make accurate low ohm measurements, short the test leads together and record the resistance reading. Deduct this value from actual readings.*

### **Measurement Procedure:**

1. Disconnect power to circuit to be measured.
2. Plug black test lead into the **COM** input jack.
3. Plug the red test lead into the **V/ $\Omega$**  input jack.
4. Set the rotary switch to the "ON" position.
5. Connect test leads to circuit to be measured.
7. Read the resistance on the TPI 100.

## MAINTENANCE

1. **Battery Replacement:** The 265 will display a battery symbol when the internal 9 Volt battery needs replacement. The battery is replaced as follows:
  - a. Disconnect and remove all test leads from live circuits and from the 265.
  - b. Loosen the screw from the back of the 265 battery cover.
  - c. Remove the battery compartment cover.
  - d. Remove old battery and replace with new battery. Observe the correct polarity on the battery.
  - e. Reassemble the instrument in reverse order from above.
2. **Cleaning your 265:**

Use a mild detergent and slightly damp cloth to clean the surfaces of the 265.



**The Value Leader™**

**[www.tpi-thevalueleader.com](http://www.tpi-thevalueleader.com)**

## 100 Instruction Manual

---

Test Products International, Inc.  
9615 SW Allen Blvd  
Beaverton, OR 97005-4814 USA  
Ph: 503-520-9197 Fax: 503-520-1225

---

Test Product International Ltd.  
342 Bronte Street South, Unit 9  
Milton, Ontario L9T 5B7  
Ph: 905-693-8558 Fax: 905-693-0888

---

Test Products International Europe  
Longley House, International Drive, Southgate  
Crawley, West Sussex RH10 6AQ  
Ph: +44 (0) 1293 561212 Fax: +44 (0) 1293 813465