



Chipsmall Limited consists of a professional team with an average of over 10 year of expertise in the distribution of electronic components. Based in Hongkong, we have already established firm and mutual-benefit business relationships with customers from,Europe,America and south Asia,supplying obsolete and hard-to-find components to meet their specific needs.

With the principle of “Quality Parts,Customers Priority,Honest Operation,and Considerate Service”,our business mainly focus on the distribution of electronic components. Line cards we deal with include Microchip,ALPS,ROHM,Xilinx,Pulse,ON,Everlight and Freescale. Main products comprise IC,Modules,Potentiometer,IC Socket,Relay,Connector.Our parts cover such applications as commercial,industrial, and automotives areas.

We are looking forward to setting up business relationship with you and hope to provide you with the best service and solution. Let us make a better world for our industry!




Contact us

Tel: +86-755-8981 8866 Fax: +86-755-8427 6832

Email & Skype: info@chipsmall.com Web: www.chipsmall.com

Address: A1208, Overseas Decoration Building, #122 Zhenhua RD., Futian, Shenzhen, China






ITEM NUMBER	TE PART NUMBER	DESCRIPTION	QTY PER KIT
1	1055439-1	Cable Fixture Sub-Assembly	1
2	1055441-1	Clamp Insert for 02.16 [.085] Cable	1 Set
3	1055547-1	Clamp Insert for 01.78 [.070] Cable	1 Set
4	91362-1	.38 [.015] Thick Solder Gage	1
5	1055460-1	Dielectric Recess Tool	1
6	1055456-1	Locator Tool, Type A	1
7	1055458-1	Dielectric Insert Tool	1
8	1055457-1	Locator Tool, Type A	1
9	1055463-1	Center Contact Holder	1
10	1055459-1	Dielectric Insert Tool	1
11	1055449-1	Locking Ring Pliers	1
12	1055464-1	Locator Tool, Type B	1
13	1055461-1	Locator Tool, Type B	1

Figure 1

1. INTRODUCTION

Solder Assembly Kit 1055466-1 for OSSM Connectors, shown in Figure 1, contains everything necessary to solder OSSM solder-style connectors to 2.16 [.085] and 1.78 [.070] diameter semi-rigid and flexible cable.



Tool directions in this document are for reference only. Refer to the appropriate connector assembly instructions to insure proper assembly. Refer to Figure 2 and Figure 3 for connector assemblies and their associated instruction sheets.




Dimensions are in metric units [with U.S. customary units in brackets], unless otherwise indicated.

SEMI-RIGID CABLE CONNECTORS		
Connector Part Number		Instruction Sheet
1046477-1		408-4776
1046479-1		408-4777
1045423-1	1055670-1	408-4792
1062251-1	1045422-1	
1045401-1		408-4793
1045381-1	1045410-1	408-4794
1058589-1		
1058588-1	1045351-1	408-4795
1045350-1	1062250-1	
1045370-1		408-4796

Figure 2

FLEXIBLE CABLE CONNECTORS		
Connector Part Number		Instruction Sheet
1045497-1		408-4788
1045496-1		408-4789
1062258-1	1045481-1	408-4790
1081231-1	1045482-1	
1045477-1	1045476-1	408-4791
1062256-1		
1062257-1	1085817-1	408-4798
1045510-1	1045511-1	
1045507-1		408-4799

Figure 3



Contact customer service or refer to Catalog 1308940 for additional information.

2. DESCRIPTION

Solder Assembly Kit 1055466-1 contains the tooling required to properly solder OSSM connectors to semi-rigid and flexible coax cable. The kit contains a cable fixture sub-assembly, two sets of clamp inserts for 2.16 [.085] and 1.78 [.070] cable, and four types of locators that are used to properly align the connector and cable. The kit also contains a solder gage for proper spacing of the center contact, a center contact holder, three dielectric insertion/recess tools, and locking ring pliers.

The cable fixture subassembly consists of a fixture frame, thumbscrew, positioning tool and spring. See Figure 4. When used with the proper clamp inserts the

assembly holds and locates coaxial cable for soldering.

3. INSTALLING/REPLACING THE CLAMP INSERT




Clamp inserts come in sets of two. Upper and lower inserts are interchangeable.

1. Select the appropriate clamp inserts. Refer to Figure 1 for the appropriate clamp inserts.
2. Remove the cable fixture thumbscrew by rotating it in a counterclockwise direction.
3. Remove the positioning tool by rotating it in a counterclockwise direction.
4. Remove the clamp inserts from the frame after the positioning tool is removed.
5. Sandwich the spring in the pockets on the replacement clamp inserts.
6. Place clamp inserts in the fixture frame and reinstall the positioning tool.
7. Retighten positioning tool.
8. Reinstall the thumbscrew.

4. TRIMMING CABLE WITH FIXTURE FRAME

The fixture frame is equipped with six trimming holes designed to remove the outer jacket and cable dielectric. The side marked with the number 2 is for trimming 1.78 [.070], 2.16 [.085], and 3.58 [.141] cable. See Figure 4 and Figure 5. When cable is fully bottomed during trimming, a strip length of 2.79 [.110] will result. If different strip lengths are required the center conductor must be trimmed separately.

The side marked with a number the number "1" is for trimming cable already mounted in a connector housing. See the connector specific instruction sheet for more information.



Trim blades are NOT included with the kit. Use a razor blade with .38 [.015] maximum thickness.

5. USING SOLDER GAGE AND CENTER CONTACT HOLDER

The center contact holder is designed to hold both male and female center contacts for OSSM connectors.

The solder gage is used to properly space the OSSM center contact away from the cable dielectric.




Figure 4




Figure 5



To avoid personal injury, be sure to observe all local safety practices (including the use of gloves). The solder gage, center contact holder, and the contact may be hot after soldering.

6. USING LOCATING TOOLS

Solder Assembly Kit 1055466-1 contains four locating tools. Refer to the connector specific instruction sheet for selection of proper locator tool and assembly instructions.

Type A, as well as Type B locating tools are available.


6.1. Using Type A Locating Tools

The solder assembly kit contains two Type A locator tools. These tools are designed to be used with the fixture subassembly. To insure proper connector assembly, follow the instructions listed below.

1. Place connector housing on end of cable sub-assembly. The subassembly refers to cable with center contact.
2. Place loose connector assembly in fixture base.
3. Nest the center contact in locator tool.
4. Tighten the thumbscrew to secure the cable.
5. Tighten the locator tool to seat the cable firmly.
6. Slide connector housing over locator tool.
7. Maintain position of housing firmly against locator tool.



Center contact holders contains small amounts of lead. The lead is used for assembly.



Maximum operating temperature for the center contact holder is 300°C [572°F].



To avoid personal injury, be sure to follow all local safety practices when using solder and solder equipment.

8. Solder according to the connector specific instructions.



Fixture should be clamped vertically in vise to keep housing seated against locator tool.

6.2. Using Type B Locating Tools

The solder assembly kit contains two Type B locator tools. These tools are used to confine the connector dielectric, which aids in providing proper cable seating when soldering to flexible cable. To insure proper connector assembly, follow connector specific instructions.

7. USING DIELECTRIC TOOLS

Solder Assembly Kit 1055466-1 contains three dielectric tools. Two dielectric (insertion) tools are used to insert the dielectric bushing into the connector housing. The dielectric (recess) tool is used to compress expanded cable dielectric after soldering semi-rigid coaxial cable to the connector housing, if required.

Use the following instruction to press the dielectric bushing into the connector subassembly.

1. Thread the insertion tool into connector subassembly.
2. Insert the dielectric into insertion tool housing.
3. Place insertion tool plunger into position.
4. Press the plunger until the flange bottoms on the tool housing.

8. USING LOCKING RING PLIERS

The locking ring pliers are used to compress the retaining ring, allowing installation of the coupling nut on specific connectors. Use the pliers as follows:

1. Place retaining ring (and gasket) on connector housing.
2. Compress the retaining ring with the retaining ring pliers.
3. Push coupling nut on to housing and over the retaining ring.
4. Check to make sure the coupling nut rotates freely after the retaining ring is in place.

9. REVISION SUMMARY

Since the previous release of this document, the new company logo was applied.