



Chipsmall Limited consists of a professional team with an average of over 10 year of expertise in the distribution of electronic components. Based in Hongkong, we have already established firm and mutual-benefit business relationships with customers from,Europe,America and south Asia,supplying obsolete and hard-to-find components to meet their specific needs.

With the principle of “Quality Parts,Customers Priority,Honest Operation,and Considerate Service”,our business mainly focus on the distribution of electronic components. Line cards we deal with include Microchip,ALPS,ROHM,Xilinx,Pulse,ON,Everlight and Freescale. Main products comprise IC,Modules,Potentiometer,IC Socket,Relay,Connector.Our parts cover such applications as commercial,industrial, and automotives areas.

We are looking forward to setting up business relationship with you and hope to provide you with the best service and solution. Let us make a better world for our industry!



Contact us

Tel: +86-755-8981 8866 Fax: +86-755-8427 6832

Email & Skype: info@chipsmall.com Web: www.chipsmall.com

Address: A1208, Overseas Decoration Building, #122 Zhenhua RD., Futian, Shenzhen, China




DRAWING MADE IN THIRD ANGLE PROJECTION
 THIS DRAWING IS UNPUBLISHED.
 © COPYRIGHT 19

RELEASED FOR PUBLICATION
 BY AMP INCORPORATED. ALL INTERNATIONAL RIGHTS RESERVED.

MOD 1
 LOC BD
 DIST 37

REV LTR
 A REDRAWN WITHOUT CHANGE

REVISIONS	DESCRIPTION	DATE	APPD
1	REDRAWN WITHOUT CHANGE	08/09/82	--



DO NOT SCALE PRINT.
 UNLESS SPECIFIED
 DIMENSIONS IN INCHES
 TOLERANCES DIM. C.005
 2 PLC DEC # 0.13 C.005
 3 PLC DEC # 2
 ANGLES # 2°

MATERIAL
 POLYESTER, NATURAL

FINISH

DR	08/08/82	L. SINE
CHK	8-9-82	B. STONE
APPD	9-9-82	A. RAYVIS
APPD	9-9-82	C. BRNKE

APPLICATION SPEC

WEIGHT

AMP
 AMP Incorporated
 Harrisburg, PA 17105-3608

KEYING PLUG, SOCKET
 HEADER, METRIMATE

SIZE B
 CASE CODE 00779
 DRAWING NO. C-211108

SCALE 20:1
 SHEET 1 OF 1

PART NO
 211108-1

CUSTOMER DRAWING

THIS DRAWING IS A CONTROLLED DOCUMENT FOR AMP INCORPORATED. IT IS SUBJECT TO CHANGE AND THE CONTROLLING ENGINEERING ORGANIZATION SHOULD BE CONTACTED FOR THE LATEST REVISION.