

Chipsmall Limited consists of a professional team with an average of over 10 year of expertise in the distribution of electronic components. Based in Hongkong, we have already established firm and mutual-benefit business relationships with customers from, Europe, America and south Asia, supplying obsolete and hard-to-find components to meet their specific needs.

With the principle of "Quality Parts, Customers Priority, Honest Operation, and Considerate Service", our business mainly focus on the distribution of electronic components. Line cards we deal with include Microchip, ALPS, ROHM, Xilinx, Pulse, ON, Everlight and Freescale. Main products comprise IC, Modules, Potentiometer, IC Socket, Relay, Connector. Our parts cover such applications as commercial, industrial, and automotives areas.

We are looking forward to setting up business relationship with you and hope to provide you with the best service and solution. Let us make a better world for our industry!



Contact us

Tel: +86-755-8981 8866 Fax: +86-755-8427 6832

Email & Skype: info@chipsmall.com Web: www.chipsmall.com

Address: A1208, Overseas Decoration Building, #122 Zhenhua RD., Futian, Shenzhen, China







1.Scope

This Specification applies to the Piezoelectric sensor for mechanical shock.

2.Standard Products

	Item	Rating
2.1	Operating temperature range	-10 ~ 60 °C
2.2	Storage temperature range	-30 ~ 80 °C
2.3	Acceleration limit	15000 m/s ² max.

3.Construction

	Item	SPEC
3.1	Appearance	No remarkable damage or stains allowed (Visual check)
3.2	Shape/Size	As per Fig.1 attached
3.3	Marking	Shape(F), Inclined Angle(2), Product serial No.

4.Electrical Performance

	Item	SPEC	Test Condition
4.1	Voltage Sensitivity (Vs)	$0.1 \text{ mV/(m/s}^2) \pm 15 \%$	100m/s^2 ,1kHz ¹⁾
4.2	Capacitance (Cp)	220 pF ± 20 %	1Vrms, 1kHz
4.3	Insulation Resistance	500 Mohm min.	10V DC, after 1min.
4.4	Resonant Frequency	25 kHz min.	
4.5	Non-linearity	5 % max.	at 500m/s ²
4.6	Incident Angle of	25 ± 3°	
	Sensitivity Axis		

1) As measured with an applied acceleration in the direction of sensitivity axis of Fig.1.

5.Mechanical Performance

	Item	SPEC	Test Method	
5.1 Electrode		No terminal electrode shall be	4.9 N from transverse	
Strength peeled off.		peeled off.	direction,10 ±0.5 s	
5.2 Bending		No outstanding damage.	PC boad deflection distance:1 mm	
Strength			(speed 1 mm/second)	
			10 ±0.5 s	
			Thickness of PC board: 1.6 mm	

	Item	SPEC	Test Method
5.3	Vibration Vs drift:within±10%		10 to 55 Hz(1 minute sweep),
		Cp drift:within±10%	Amplitude:1.5 mm,
			2 hours each direction
5.4	Solderability	More than 3/4 of the soldered area	Pre-heat:150 ±10 °C,1~2 minutes
		of the terminal electrodes shall be	Soldering:230 ±5 °C,3 ±0.5 s
		covered with new sold	
5.5	Soldering heat	Vs drift:within±10%	Refolw soldering once
	resistance	Cp drift:within±10%	240°C peak ,over 220°C 10s max.
			Pre-heating 140 ±10 °C 1~2min.
5.6	Shock	Vs drift:within±10%	15000 m/s, 0.5msec half sinusoidal
		Cp drift:within±10%	wave ,5 times each direction


6.Environmental Performance

	Item	SPEC	Test Method			
6.1	Dry heat	Vs drift:within±10%	85 ±2 °C,500 hours			
		Cp drift :within±10%				
6.2	Cold	Vs drift:within±10%	-40 ±3°C,500 hours			
		Cp drift :within±10%				
6.3	Damp heat	Vs drift:within±10%	40 ±2 °C,90~95 %RH, 500 hours			
		Cp drift :within±10%				
6.4	Heat cycle	Vs drift:within±10%	-40 ±3 °C~ RT ~85 ±3 °C~ RT			
		Cp drift :within±10%	30min 2min 30min 2min 5cycles			
6.5	Temperature	Vs drift:within±10%	-10 ~ 60 °C			
		Cp drift :within±20%				

SPECIFICATIONS	DATE	Sep. 1,	1999
151 - EFJ -G25F02	APPROVAL	CHECK	DESIGN
Piezoelectric sensor for mechanical shock			
EFJG25EF01	S.kawamura		T.Ninomiya
	51 - EFJ -G25F02 Piezoelectric sensor for mechanical shock	51 - EFJ -G25F02 APPROVAL Piezoelectric sensor for mechanical shock	51 - EFJ -G25F02 APPROVAL CHECK Piezoelectric sensor for mechanical shock

Item		Test Method				
Sta	andard test	20°C 65% RH,1.013×10 ⁵ Pa as a rule;however,if there occurs no doubt about judgement,				
conditions		the test may be performed at $15\sim35^{\circ}$ C, $25\sim85\%$ RH and $0.860\times10^{5}\sim1.060\times10^{5}$ Pa				
4.1	Voltage sensitivity	See Fig.2				
5.1	Electrode	Solder the external electrodes to the PC board so that the marking side of a				
	Strength	product is located upper, and apply the specified load from one side of the product				
		to maintain the conditions for a given period of time.				
5.2	Bending Strength	Solder the external electrodes to the PC board so that the marking side of a product is located upper, and deflect the PC board at 90 mm span and deflection distance 1 mm.				
5.3	Vibration	Repeat the vibration at specified frequency and specified oscillation amplitude,				
		and apply it in X.Y.Z directions orthogonal to the sample for the specified time				
		with one minute as a cycle.				
5.4	Solderability	Dip a product preheated as specified in the solder bath maintained at the specified				
		temperature so that the electrode is completely hidden for a given period of time.				
		Solder shall be H63A(eutectic solder JIS-Z-3282) or Sn-Pb solder including 2 to				
		5 % of Ag, the flux shall be rosin (JIS-K-5902) methanol (JIS-K-1501) solution				
		and the weight ratio shall be approx.25%.				
5.5	Soldering	After passing the sample through the reflow furnace maintained at the specified				
	heat	temperature and time, take it out in the room temperature, and after leaving it for				
	resistance	8 hours, measure the characteristics.				
5.6	Shock	After Dropping specified times and directions, measure the characteristics.				
6.1	Dry heat	After leaving a product in the thermostatic oven maintained at the specified				
		temperature for the specified time, take it out in the room temperature, and after				
		leaving it for 8 hours, measure the characteristics.				
6.2	Cold	After leaving a product in the thermostatic oven maintained at the specified				
		temperature for the specified time, take it out in the room temperature, and after				
		leaving it for 8 hours, measure the characteristics.				
6.3	Damp heat	After leaving a product in the thermostatic oven maintained at the specified				
		temperature and humidity for the specified time, take it out in the room				
		temperature, and after leaving it for 8 hours, measure the characteristics.				
6.4	Heat cycle	After repeating the specified cycle by the specified frequency, take it out in the				
		room temperature, and after leaving it for 8 hours, measure the characteristics.				

Figure 1 (5 - 2)



Remark) When an acceleration is applied in the direction of A axis, positive voltage occurs at electrode 1.

(Unit:mm)

Serial No.

month year	1	2	3	4	5	6	7	8	9	10	11	12
1999	а	b	С	d	е	f	9	h	j	B	l	m
2000	n	P	F	r	Q	t	u	U	W	χ	y	8
2001	Α	В	С	D	Ε	F	G	Н	J	Κ	L	М
2002	N	Р	Q	R	S	Τ	U	٧	W	Χ	Υ	Z

7.Operating Precautions

7.1 Application

This piezoelectric sensor is designed for use in domestic electric appliances, AV. equipment, OA equipment, communication equipment, measuring equipment and general electronic equipment. Check with us separately, for use in equipment which needs high reliability (such as automobiles, aircraft, medical equipment and space equipment).

7.2 Precautions for Handling

7.2.1 Precautions for Safety

(1) Fail-safe Design for Equipment

In application of the piezoelectric sensor, it is recommended that equipment shall be protected by adding a protective and/or retarding design circuit against deterioration and failures of the piezoelectric sensor.

(2) Operating Temperature Ranges

This piezoelectric sensor shall not be operated beyond the specified "Operating Temperature Range" in the Specifications.

(3) Changes/Drifts in Voltage Sensitivity

It shall be noted that voltage sensitivity of the piezoelectric sensor may drift depending IC applied (the type names, the manufacturer) and resistance values of external resisters and the circuit design.

(4) Stray Capacitance

Stray capacitance and insulation resistance on printed circuit board may cause abnormalities of the piezoelectric sensor such as the voltage sensitivity and the frequency characteristic.

Attention shall be paid to those abnormalities above mentioned in circuit design.

(5) Direct Voltage

Avoid directly applying a direct voltage to the piezoelectric sensor.

7.2.2 Prohibited Applications

- (1) "Flow Soldering" shall not be applied to the piezoelectric sensor.
- (2) "Ultrasonic Cleaning" and "Ultrasonic Welding" shall not be applied to the piezoelectric sensor for preventing them from electrical failures and mechanical damages.
- (3) Avoid water washing after soldering.
- 7.2.3 Application Notes
- (1) Handling precautions
- Abnormal/excess electrical stresses such as over voltage spikes and electrostatic discharges may
 cause electrical deterioration's and failures of the piezoelectric sensor and affect reliability of
 the devices.
- 2) If the product is drooped or a strong stress is applied to it, it nay break.

Do not use the products which strong stress have been applied.

(2) Automated Assembly

For automatic inserting, make sure to make inserting checks by means of the inserting machine in advance. In inserting the product, unsuitable chucking force or inserting speed may apply so excessive impulse to break the product.

Avoid inserting using mechanical-chuck-type inserting machine. Also, for the inserting machine using other method, select the low speed.

Please contact us for details.

- (3) Soldering in PC boards and washing after soldering
 - The product is applicable to refold soldering. Conditions of the soldering temperature and time are recommended as shown below.

Preheating temperature : 175°C 220
Preheating time : 1-2 minutes
Soldering temperature : 220°C
Soldering time : 20 sec max.
Peak temperature : 250°C max.

2) Take care that a soldering iron does not contact with the product body (out case).

For manual soldering, the maximum soldering temperature and time should be 300° C and 3 seconds.

3) Rosin-based and non-activated soldering flux is recommended.

The content of halogen in the flux shall be 0.1 wt. or less.

4) Post Soldering Cleaning

Application of ultrasonic cleaning is prohibited.

 $Cleaning\ Conditions\ such\ as\ kinds\ of\ cleaning\ solvents, immersion\ times\ and\ temperatures\ etc.$

shall be checked by experiments before production.

(4) Maintenance and using environment

Avoid maintenance and use in the following environments.

- 1) Corrosive gaseous atmospheres (Cl2, NH3, SO2, Ox etc.)
- 2) Dusty places
- 3) Places exposed to direct sunlight
- 4) Places over which water is splashed
- 5) To be exposed directly to water
- 6) Places exposed to briny air
- 7) Places apt to be affected by static electricity or electric field strength
- (5) Long Term Storage

The piezoelectric sensor shall not be stored under severe conditions of high temperatures and high humidifies.

Store them indoors under 40°C max, and 75% RAH max. Use them within one year and check the solderability before use. And avoid maintenance and use in the following environments.

- 1) Corrosive gaseous atmospheres (Cl2, NH3, SO2, Ox etc.)
- 2) Places exposed to direct sunlight
- 3) Places where dew is apt exposed to condense
- 7.3 The design is subject to change for improvement of quality.

8.Embossed tape Packaging


8.1 Applicable Standard

JIS C 0806


- 8.2 Specifications
- 8.2.1 Dimensions
- (1) Carrier Tape: Figure 3
- (2) Reel: Figure 4
- (3) The product shall be packed properly not to be damaged during transportation and storage.
- 8.2.2 Reeling Quantity

2000 pcs/reel

- 8.2.3 Taping structure
- (1) The tape shall be wound around the reel in the direction shown below.



(2) Leader part and vacant position



Tape running_direction

8.4 Marking

The following items shall be marked at least on the side of the reel.

- (1) Part Number
- (2) Quantity
- (3) Lot Number
- (4) Manufacturer's Name


8.5 Tape Specifications

- (1) Tensile Strength of Carrier Tape: 9.8N min.
- (2) Top Cover Tape Adhesion (See the below figure.)

Pull off Angle : 0~15°

Speed : 300 + 0 mm/minute

Force : 0.19~0.69N



(3) Missing Parts

The maximum number of missing parts shall not exceed 0.1% per reel and continuous missing shall not be more than 3 parts.

Figure 2 Test Method of measuring Voltage Sensitivity





Figure 3 Carrier Tape Dimensions




W	F	Е	P1	P2	P0	D0	t1	t2
12.0	5.5	1.75	4.0	2.0	4.0	1.5 +0.1 -0	0.60	1.70
±0.3	±0.1	±0.1	±0.1	±0.1	±0.1		max.	max.

A	В
2.6	5.4
±0.2	±0.2

Unit:mm

Figure 4 Reel Dimensions



A	В	С	D	Е	W
180±5	60min.	13.0±0.2	21±0.8	2±0.5	12.4 +2.0

T	t	r
18.4max	3max	1.0

Uint:mm