imall

Chipsmall Limited consists of a professional team with an average of over 10 year of expertise in the distribution of electronic components. Based in Hongkong, we have already established firm and mutual-benefit business relationships with customers from, Europe, America and south Asia, supplying obsolete and hard-to-find components to meet their specific needs.

With the principle of "Quality Parts, Customers Priority, Honest Operation, and Considerate Service", our business mainly focus on the distribution of electronic components. Line cards we deal with include Microchip, ALPS, ROHM, Xilinx, Pulse, ON, Everlight and Freescale. Main products comprise IC, Modules, Potentiometer, IC Socket, Relay, Connector. Our parts cover such applications as commercial, industrial, and automotives areas.

We are looking forward to setting up business relationship with you and hope to provide you with the best service and solution. Let us make a better world for our industry!



Contact us

Tel: +86-755-8981 8866 Fax: +86-755-8427 6832 Email & Skype: info@chipsmall.com Web: www.chipsmall.com Address: A1208, Overseas Decoration Building, #122 Zhenhua RD., Futian, Shenzhen, China



HS Dock™ Plug Extractor Kit



Application Tooling Specification Sheet



Order No. 62202-0220

FEATURES

This tool is designed for the removal of wafers from an HS Dock[™] plug connector assembled to a printed circuit board.

SCOPE

<u>Products</u>: 1.20mm by 3.50mm Pitch Plateau HS Dock[™] Plug, Right Angle, 72 Circuits. See Product List below for specific part numbers.


Product List

The following is a partial list of the product order numbers and their specifications this tool is designed to run. Updates to this list are available on <u>www.molex.com</u>.

Series No.	Circuit Size	Assembly Order Number				
75018	72	75018-0100	75018-0301	75018-0305	75018-4100	75018-7100


Tool Operation

1. Place the Upper Housing Puller over the connector, ensuring the two tabs are behind both ends of the shroud and the support legs are aligned over the front edge of the PCB. See Figure 1.




2. Rotate the thumbscrew clockwise so the upper housing will be pulled away from the connector. After the housing is loose, rotate the thumbscrew counterclockwise to remove the Upper Housing Puller and finish removing (by hand) the upper housing from the connector. See Figure 2.

Release Date: 01-21-09 Revision Date: 10-08-13 **UNCONTROLLED COPY**





- 3. Press down on the front of the retention clip by hand or use a small, piece of flat stock. It will become loose enough to remove it by hand. See Figure 3.
- 4. Rotate the thumbscrew of the Wafer Extractor counter-clockwise to open the tool. Slide the tool over the first wafer by capturing the tips of the wafer in the three corresponding pockets, (these pockets will hook under the wafer being removed). This will align the support legs over two adjacent wafers and the lower housing. See Figure 4.










Figure 4

5. Rotate the thumbscrew clockwise to pull the wafer from the PCB. When an audible "click" is heard, this indicated the wafer has been extracted. Discard the extracted wafer. See Figure 5.




Doc No: ATS-622020220 Revision: B Release Date: 01-21-09 Revision Date: 10-08-13 **UNCONTROLLED COPY**

- 6. Load the new wafer in the empty cavity of the lower housing.
- 7. Align the wafer tips to the edge of the compression pad on the Wafer Press. Make sure the plunger of the press is approximately in the center so the wafer will be engaged. Pull down the toggle clamp until the wafer is completely seated. See Figure 6.



COMPRESSION PAD

- Install the retention clip to the lower housing by aligning the holes in the stiffener to the bosses in the lower housing. While holding the stiffener in place, slide the upper housing on until it just starts to engage the stiffener. See Figure 7.
- Place the Upper Housing/Retention Clip Press over the connector ensuring the moveable bar is in front of the connector. Rotate the two thumbscrews counterclockwise until resistance is felt with both thumbscrews. Now the moveable bar is aligned with the upper housing. Continue rotating the thumbscrews simultaneously until they stop. See Figure 8.
- 10. To open the tool, rotate thumbscrews clockwise until they stop. Remove the clip press from the connector.



CAUTION: Molex application tooling specifications are valid only when used with Molex connectors and tooling.

Contact Information

For more information on Molex application tooling please contact Molex at 1-800-786-6539.

Visit our Web site at http://www.molex.com

Release Date: 01-21-09 Revision Date: 10-08-13 **UNCONTROLLED COPY**