



Chipsmall Limited consists of a professional team with an average of over 10 year of expertise in the distribution of electronic components. Based in Hongkong, we have already established firm and mutual-benefit business relationships with customers from Europe, America and south Asia, supplying obsolete and hard-to-find components to meet their specific needs.

With the principle of "Quality Parts, Customers Priority, Honest Operation, and Considerate Service", our business mainly focus on the distribution of electronic components. Line cards we deal with include Microchip, ALPS, ROHM, Xilinx, Pulse, ON, Everlight and Freescale. Main products comprise IC, Modules, Potentiometer, IC Socket, Relay, Connector. Our parts cover such applications as commercial, industrial, and automotives areas.

We are looking forward to setting up business relationship with you and hope to provide you with the best service and solution. Let us make a better world for our industry!



Contact us

Tel: +86-755-8981 8866 Fax: +86-755-8427 6832

Email & Skype: info@chipsmall.com Web: www.chipsmall.com

Address: A1208, Overseas Decoration Building, #122 Zhenhua RD., Futian, Shenzhen, China

INSTRUCTION MANUAL MANUAL DE INSTRUCCIONES MANUEL D'INSTRUCTIONS



GREENLEE®


A Textron Company

GT-65 • GT-95

**Voltage and
Continuity
Testers**

**Verificadores
de tensión y
continuidad**

**Contrôleurs de
tension et de
continuité**



Read and understand all of the instructions and safety information in this manual before operating or servicing this tool.



Lea y entienda todas las instrucciones y la información sobre seguridad que aparecen en este manual, antes de manejar esta herramienta o darle mantenimiento.

Lire attentivement et bien comprendre toutes les instructions et les informations sur la sécurité de ce manuel avant d'utiliser ou de procéder à l'entretien de cet outil.



GREENLEE®

Description

The Greenlee GT-65 and GT-95 Voltage and Continuity Testers are intended to measure voltage and verify continuity. Each model has LEDs to indicate common voltages. They also have non-contact and single-probe voltage detection capability.

In addition, the GT-95 has an easy-to-read LCD and a shaker to signal AC voltage measurement. This model can trip a ground-fault circuit interrupter (GFCI). The LEDs glow green at low voltage, and change to red when the measured voltage presents a shock hazard.

Both models have an indicator self-test feature that allows the user to verify the functionality of the voltage-indicating LEDs, the continuity beeper, and the GT-95 LCD.

Safety

Safety is essential in the use and maintenance of Greenlee tools and equipment. This instruction manual and any markings on the tool provide information for avoiding hazards and unsafe practices related to the use of this tool. Observe all of the safety information provided.

Purpose of This Manual

This instruction manual is intended to familiarize all personnel with the safe operation and maintenance procedures for the Greenlee GT-65 and GT-95 Voltage and Continuity Testers.

Keep this manual available to all personnel. Replacement manuals are available upon request at no charge.

All specifications are nominal and may change as design improvements occur. Greenlee Textron Inc. shall not be liable for damages resulting from misapplication or misuse of its products.

® Registered: The color green for electrical test instruments is a registered trademark of Greenlee Textron Inc.

KEEP THIS MANUAL

Important Safety Information



SAFETY ALERT SYMBOL

This symbol is used to call your attention to hazards or unsafe practices which could result in an injury or property damage. The signal word, defined below, indicates the severity of the hazard. The message after the signal word provides information for preventing or avoiding the hazard.

⚠ DANGER

Immediate hazards which, if not avoided, WILL result in severe injury or death.

⚠ WARNING

Hazards which, if not avoided, COULD result in severe injury or death.

⚠ CAUTION

Hazards or unsafe practices which, if not avoided, MAY result in injury or property damage.



⚠ WARNING

Read and understand this material before operating or servicing this equipment. Failure to understand how to safely operate this tool could result in an accident causing serious injury or death.



GREENLEE

Important Safety Information



⚠ WARNING

Electric shock hazard:

Contact with live circuits could result in severe injury or death.

⚠ WARNING

Electric shock and fire hazard:

- Do not expose this unit to rain or moisture.
- Do not use the unit if it is wet or damaged.
- Use test leads or accessories that are appropriate for the application. Refer to the category and voltage rating of the test lead or accessory.
- Inspect the test leads or accessory before use. They must be clean and dry, and the insulation must be in good condition.
- Use this unit for the manufacturer's intended purpose only, as described in this manual. Any other use can impair the protection provided by the unit.

Failure to observe these warnings could result in severe injury or death.

⚠ WARNING

Electric shock hazard:

- Do not apply more than the rated voltage between any two input terminals, or between any input terminal and earth ground.
- Do not contact the test lead tips or any uninsulated portion of the accessory.

Failure to observe these warnings could result in severe injury or death.

⚠ WARNING

Electric shock hazard:

- Do not operate with the case or battery cover open.
- Before opening the case or battery cover, remove the test leads from the circuit and shut off the unit.

Failure to observe these warnings could result in severe injury or death.

Important Safety Information

⚠ WARNING

Electric shock hazard:

- Unless measuring voltage, shut off and lock out power. Make sure that all capacitors are discharged. Voltage must not be present.
- Using this unit near equipment that generates electromagnetic interference can result in unstable or inaccurate readings.

Failure to observe these warnings could result in severe injury or death.

⚠ CAUTION

Electric shock hazard:

Do not change the measurement function while the test leads are connected to a component or circuit.

Failure to observe this precaution may result in injury and can damage the unit.

⚠ CAUTION

Electric shock hazard:

When testing GFCIs installed in two-wire systems (no ground wire available), the tester may give a false indication that the GFCI is not functioning properly. If this occurs, recheck the operation of the GFCI using the test and reset buttons. The GFCI test button feature will demonstrate proper operation.

Failure to observe this precaution may result in injury and can damage the unit.

⚠ CAUTION

Electric shock hazard:

- Do not attempt to repair this unit. It contains no user-serviceable parts.
- Do not expose the unit to extremes in temperature or high humidity. Refer to "Specifications."


Failure to observe these precautions may result in injury and can damage the unit.



GREENLEE®


Identification

1. Non-contact voltage detection (EF) antenna
2. Non-contact voltage detection (EF) LED
3. Non-contact voltage detection (EF) button
4. Display (GT-95 only)
5. LEDs
6. GFCI test button (GT-95 only)
7. Negative, common (COM), or ground input terminal for all measurements
8. Positive (+) input terminal for all measurements



Display Icons

9. DC volts
10. Auto-Hold is activated
11. AC volts
12. Polarity indicator
13. Low battery indicator



Symbols on the Unit

- Warning—Read the instruction manual
- Risk of electric shock
- Double insulation

Using the Features

- **EF** Press and hold to detect the electric field that surrounds current-carrying conductors. The EF LED will blink once, and the beeper will emit a short sound. Signal strength is indicated by tone and flashing of the EF LED. For the GT-95, signal strength is also displayed as a series of dashes on the display.
 - Use the tester's built-in antenna (refer to the "Identification" section on the previous page) for tracing live circuits or locating a break in a wire.
 - For more precision, such as distinguishing between current-carrying and ground wires, connect a test lead to the + input terminal and use it as a probe.
- **Auto-Hold** This feature automatically activates when the tester is removed after making a voltage reading. The LEDs flash the last measured value for 10 seconds. The GT-95 LCD holds the last measured value and displays the  icon.
- **Oversupply Warning** The 1000 VAC/380 VDC LED flashes if these levels are exceeded. The GT-95 LCD displays "OL" above 1000 V AC or DC.
- **Indicator Self-Test** Short the two test leads together. The Continuity LED will light, and the beeper will sound. With the leads still shorted, press and hold the **EF** button. The beeper will turn off. The 13 voltage-indicating LEDs will illuminate for approximately 2 to 3 seconds and then turn off. On the GT-95, five of the LEDs will change from green to red, and all the digits and icons in the LCD will be visible. At the conclusion of the test, the Continuity LED and beeper will then turn back on.
- **Shock Hazard Warning (GT-95 only)** The voltage LEDs are red if the measured voltage is above 54 VDC/30 VAC. Below these levels, the LEDs are green.
- **Shaker (GT-95 only)** If enabled, the shaker signals that an AC voltage greater than approximately 19 V is present between the test leads. To enable or disable this feature, remove the leads from any voltage or continuity source. Press and hold first the **GFCI** button and then the **EF** button.
 - The shaker will remain on until the buttons are released to confirm that this feature is enabled.
 - The shaker will turn on briefly to signal that this feature has been disabled.



Operation



⚠️ WARNING

Electric shock hazard:

Contact with live circuits could result in severe injury or death.

⚠️ CAUTION

Electric shock hazard:

Do not change the measurement function while the test leads are connected to a component or circuit.

Failure to observe this precaution may result in injury and can damage the unit.


1. Refer to "Typical Measurements" for specific measurement instructions.
2. Refer to the Test Table for test instructions.
3. Perform the Indicator Self-Test as described in "Using the Features." Test the unit on a known functioning circuit or component.
 - If the unit does not function as expected on a known functioning circuit, replace the battery.
 - If the unit still does not function as expected, send the unit to Greenlee for repair. Refer to the instructions under the Warranty.
4. Take the reading from the circuit or component to be tested. The LEDs illuminate as shown in the LED Table.

Operation (cont'd)

Test Table

| To test/verify this value: | Connect the red lead to: | Connect the black lead to: | The tester will indicate: |
|----------------------------|---------------------------------|---------------------------------|--|
| Continuity | Component or circuit under test | Component or circuit under test | Tone for resistance of 0 to 50 kΩ (approximately) |
| AC voltage | Component or circuit under test | Component or circuit under test | Voltage of 15 V or greater* |
| DC voltage | Component or circuit under test | Component or circuit under test | Voltage of 4.5 V or greater, plus polarity* |
| GFCI (GT-95 only) | Hot or live conductor | Earth ground | Refer to "Typical Measurements" for complete testing instructions. |

* GT-95 also displays voltage on LCD.



LED Table


| LED Illuminated | Indication |
|--------------------|----------------------------------|
| LED 1 | Positive (+) DC of 4.5 V or more |
| LED 2 | Negative (-) DC of 4.5 V or more |
| LED 3 | AC of 15 V or more |
| LED 4 only | Continuity present |
| Other voltage LEDs | Approximate voltage level |




GREENLEE®

Typical Measurements


Continuity Check



Voltage Measurement



Electric Field Detection (EF)




Refer to
“Using the Features”
for complete
instructions.

A—Non-contact
OR
B—Contact

Typical Measurements

GFCI Test (GT-95 only)

1. Consult the GFCI manufacturer's installation instructions to determine that the GFCI is installed in accordance with the manufacturer's specifications.
 2. Check for correct wiring of the receptacle and all remotely connected receptacles on the branch circuit.
 3. Operate the test button on the GFCI installed in the circuit. The GFCI must trip.
 - If the GFCI does not trip, do not use the circuit. Consult an electrician.
 - If the GFCI does trip, reset the GFCI. Then connect the GT-95 to the receptacle to be tested, as shown.
 4. Press the **GFCI** button on the GT-95 for a minimum of 6 seconds when testing the GFCI condition.
 - The Continuity/GFCI LED will turn on when the GFCI button is depressed. It will turn off when the GFCI trips.
 - If the GT-95 fails to trip the GFCI, it suggests:
 - A wiring problem with a totally operable GFCI, or
 - proper wiring with a faulty GFCI.
- Consult an electrician to check the condition of the wiring and GFCI.



CAUTION

Electric shock hazard:

When testing GFCIs installed in two-wire systems (no ground wire available), the tester may give a false indication that the GFCI is not functioning properly. If this occurs, recheck the operation of the GFCI using the test and reset buttons. The GFCI button test function will demonstrate proper operation.

Failure to observe this precaution may result in injury and can damage the unit.



GREENLEE®

Specifications and Accuracy

Polarity: Automatic

Voltage Range: 19 to 1000 VAC, 5 to 1000 VDC

Internal Basic Load: 0.8 W at 600 V (approximate)

Input Impedance: 460 kΩ || 160 pF (nominal)

Number of LEDs: 14

LED Threshold: The following table gives nominal thresholds.

AC Tolerance: \pm (2.5% of reading + 4 V)

DC Tolerance: \pm (1% of reading + 2 V)

| AC Marking | AC Threshold | DC Marking | DC Threshold |
|-------------------|---------------------|-------------------|---------------------|
| 24 | 19 | 6 | 5 |
| 48 | 38 | 12 | 10 |
| 120 | 96 | 24 | 19 |
| 208 | 166 | 36 | 30 |
| 240 | 224 | 48 | 42 |
| 277 | 259 | 60 | 54 |
| 347 | 312 | 72 | 66 |
| 480 | 414 | 110 | 91 |
| 600 | 540 | 220 | 176 |
| 1000 | 800 | 380 | 304 |

Frequency Range: DC and 45 to 65 Hz

Test Current: Less than 2.5 mA

Wireless Electric Field Detection (EF):

Indication: Bar graph segments and audible beep tones are proportional to the field strength.

Detection Frequency: 50/60 Hz

Detection Antenna: Top of unit

| Typical Voltage | GT-95 Bar Graph Indication |
|------------------------|-----------------------------------|
| 15 V to 55 V | — |
| 30 V to 95 V | -- |
| 55 V to 170 V | --- |
| above 120 V | ---- |

Specifications and Accuracy (cont'd)

Continuity Test: 0 to 50 kΩ

Test Current (typical): 0.7 µA

Open Circuit Voltage: Less than 2.0 VDC

Indication: Tone and LED

GFCI Test (for 120 V nominal circuits only—GFCI test is disabled above 132 V and below 80 V):

Test Current: 7.5 mA nominal at 120 V

Impedance: 16 kΩ nominal

Internal Load: 0.9 W @ 120 V

Operating/Storage Conditions: -10 °C to 50 °C (14 °F to 122 ° F)

0% to 85% relative humidity

Altitude: 2000 m (6500') maximum

Pollution Degree: 2

Indoor use only

Remove batteries before storing.

Battery: Two 1.5 V batteries (AAA, NEDA 24A or IEC LR03)

Measurement Categories: CAT IV, 600 V / CAT III, 1000 V per UL 61010

GT-95 Only

Display: 3-digit LCD (999 maximum count)

Display Turn-on Voltage: 15 VAC, 5 VDC (nominal)

Voltage Resolution: 1 V (AC or DC)

LCD Accuracy:

ACV: ± (2.5% of reading + 4 V)

DCV: ± (1% of reading + 2 V)



Measurement Categories

These definitions were derived from the international safety standard for insulation coordination as it applies to measurement, control, and laboratory equipment. These measurement categories are explained in more detail by the International Electrotechnical Commission; refer to either of their publications: IEC 61010-1 or IEC 60664.

Measurement Category I

Signal level. Electronic and telecommunication equipment, or parts thereof. Some examples include transient-protected electronic circuits inside photocopiers and modems.

Measurement Category II

Local level. Appliances, portable equipment, and the circuits they are plugged into. Some examples include light fixtures, televisions, and long branch circuits.

Measurement Category III

Distribution level. Permanently installed machines and the circuits they are hard-wired to. Some examples include conveyor systems and the main circuit breaker panels of a building's electrical system.

Measurement Category IV

Primary supply level. Overhead lines and other cable systems. Some examples include cables, meters, transformers, and other exterior equipment owned by the power utility.

Statement of Conformity

Greenlee Textron Inc. is certified in accordance with ISO 9000 (2000) for our Quality Management Systems.

The instrument enclosed has been checked and/or calibrated using equipment that is traceable to the National Institute for Standards and Technology (NIST).

Maintenance

⚠ CAUTION

Electric shock hazard:

- Do not attempt to repair this unit. It contains no user-serviceable parts.
- Do not expose the unit to extremes in temperature or high humidity. Refer to "Specifications."

Failure to observe these precautions may result in injury and can damage the unit.

Battery Replacement

⚠ WARNING

Electric shock hazard:

- Do not operate with the case or battery cover open.
- Before opening the case or battery cover, remove the test leads from the circuit and shut off the unit.

Failure to observe these warnings could result in severe injury or death.

1. Disconnect the unit from the circuit.
2. Remove the two screws from the battery cover.
3. Remove the battery cover.
4. Replace the batteries (observe polarity).
5. Replace the cover and screws.

Cleaning

Periodically wipe the case with a damp cloth and mild detergent; do not use abrasives or solvents.



GREENLEE

Descripción

Los Verificadores de tensión y continuidad GT-65 y GT-95 de Greenlee han sido diseñados para medir tensión y verificar continuidad. Cada modelo incluye diodos emisores de luz (LED) para indicar tensiones comunes. Incluyen además la capacidad para detectar la tensión sin hacer contacto o con una sola sonda.

Asimismo, el modelo GT-95 cuenta con una pantalla de cristal líquido (LCD) fácil de leer y un vibrador para indicar mediciones de tensión de CA. Este modelo puede accionar un interruptor de circuito de falla a tierra (GFCI). Los diodos emisores de luz (LED) brillan de color verde a tensiones bajas y cambian a color rojo cuando la tensión medida representa un peligro de descarga eléctrica.

Ambos modelos incluyen una función de autoverificación del indicador que le permite al usuario verificar la funcionalidad de los diodos emisores de luz (LED) indicadores de tensión, el emisor de tono audible de continuidad y la pantalla de cristal líquido (LCD) de la unidad GT-95.

Acerca de la seguridad

Es fundamental observar métodos seguros al utilizar y dar mantenimiento a las herramientas y equipo Greenlee. Este manual de instrucciones y todas las marcas que ostenta la herramienta le ofrecen la información necesaria para evitar riesgos y hábitos poco seguros relacionados con su uso. Siga toda la información sobre seguridad que se proporciona.

Propósito de este manual

Este manual de instrucciones tiene como propósito familiarizar a todo el personal con los procedimientos de operación y mantenimiento seguros para los Verificadores de tensión y continuidad, modelos GT-65 y GT-95 de Greenlee.

Manténgalo siempre al alcance de todo el personal. Puede obtener copias adicionales de manera gratuita, previa solicitud.

Todas las especificaciones son nominales y pueden cambiar conforme tengan lugar mejoras de diseño. Greenlee Textron Inc. no se hace responsable de los daños que puedan surgir de la mala aplicación o mal uso de sus productos.

® Registrado: El color verde para instrumentos de verificación eléctricos es una marca registrada de Greenlee Textron Inc.

CONSERVE ESTE MANUAL

Importante Información sobre Seguridad



SÍMBOLO DE ALERTA SOBRE SEGURIDAD

Este símbolo se utiliza para indicar un riesgo o práctica poco segura que podría ocasionar lesiones o daños materiales. Cada uno de los siguientes términos denota la gravedad del riesgo. El mensaje que sigue a dichos términos le indica cómo puede evitar o prevenir ese riesgo.

⚠ PELIGRO

Peligros inmediatos que, de no evitarse, OCASIONARÁN graves lesiones o incluso la muerte.

⚠ ADVERTENCIA

Peligros que, de no evitarse, PODRÍAN OCASIONAR graves lesiones o incluso la muerte.

⚠ ATENCIÓN

Peligro o prácticas peligrosas que, de no evitarse, PUEDEN OCASIONAR lesiones o daños materiales.



⚠ ADVERTENCIA

Lea y entienda este documento antes de manejar esta herramienta o darle mantenimiento. Utilizarla sin comprender cómo manejarla de manera segura podría ocasionar un accidente y, como resultado de éste, graves lesiones o incluso la muerte.



Importante Información sobre Seguridad



▲ADVERTENCIA

Peligro de electrocución:

El contacto con circuitos activados podría ocasionar graves lesiones o incluso la muerte.

▲ADVERTENCIA

Peligro de electrocución e incendio:

- No exponga esta unidad ni a la lluvia ni a la humedad.
- No utilice esta unidad si se encuentra mojada o dañada.
- Utilice cables de prueba y accesorios que sean apropiados para la aplicación que se va a realizar. Consulte la información sobre categoría y tensión nominal del cable de prueba o el accesorio.
- Revise minuciosamente los cables de prueba o el accesorio, antes de utilizarlos. Deberán estar limpios y secos, y su forro aislante deberá hallarse en buenas condiciones.
- Utilícela únicamente para el propósito para el que ha sido diseñada por el fabricante, tal como se describe en este manual. Cualquier otro uso puede menoscabar la protección proporcionada por la unidad.

De no observarse estas advertencias podrían sufrirse graves lesiones o incluso la muerte.

▲ADVERTENCIA

Peligro de electrocución:

- No aplique más de la tensión nominal entre dos terminales de entrada cualesquiera, o entre una terminal de entrada cualquiera y una conexión a tierra.
- No toque las puntas de los cables de prueba ni ninguna parte del accesorio que carezca de forro aislante.

De no observarse estas advertencias podrían sufrirse graves lesiones o incluso la muerte.

▲ADVERTENCIA

Peligro de electrocución:

- No haga funcionar esta unidad con la caja o la tapa del compartimiento de las pilas abierta.
- Antes de abrir la caja o la tapa del compartimiento de las pilas, retire del circuito los cables de prueba y apague la unidad.

De no observarse estas advertencias podrían sufrirse graves lesiones o incluso la muerte.

Importante Información sobre Seguridad

⚠ ADVERTENCIA

Peligro de electrocución:

- A menos que vaya a medir tensión, apague y bloquee la energía. Asegúrese de que todos los condensadores estén totalmente sin carga. No debe haber tensión alguna.
- Al utilizar esta unidad cerca de equipo que genere interferencia electromagnética quizás se obtenga una lectura inexacta e inestable.

De no observarse estas advertencias podrían sufrirse graves lesiones o incluso la muerte.

⚠ ATENCIÓN

Peligro de electrocución:

No cambie la función de medición mientras los cables de prueba estén conectados a un componente o circuito.

De no observarse esta advertencia pudieran sufrirse lesiones o daños a la unidad.

⚠ ATENCIÓN

Peligro de electrocución:

Al verificar interruptores de circuito de falla a tierra (GFCI) en sistemas bifilares (sin cable de conexión a tierra), el verificador podría indicar erróneamente que el GFCI no está funcionando de manera correcta. Si esto sucede, vuelva a verificar el funcionamiento del GFCI mediante los botones de prueba y restablecimiento. La función del botón de prueba del GFCI demostrará el funcionamiento correcto.

De no observarse esta advertencia pudieran sufrirse lesiones o daños a la unidad.

⚠ ATENCIÓN

Peligro de electrocución:

- No intente reparar esta unidad, ya que contiene partes que deben recibir mantenimiento por parte de un profesional.
- No exponga la unidad a ambientes de temperatura extrema o altos niveles de humedad. Consulte la sección "Especificaciones".


De no observarse estas precauciones pudieran sufrirse lesiones o daños a la unidad.



GREENLEE®


Identificación

1. Antena de detección de tensión sin hacer contacto (EF)
2. LED de detección de tensión sin hacer contacto (EF)
3. Botón de detección de tensión sin hacer contacto (EF)
4. Pantalla (Modelo GT-95 solamente)
5. Diodos emisores de luz (LED)
6. Botón de prueba de GFCI (Modelo GT-95 solamente)
7. Terminal de entrada a tierra, común (COM), o negativa, para todo tipo de mediciones
8. Terminal de entrada positiva (+) para todas las mediciones



Iconos de la pantalla

9. Voltios de CC
10. Se activa la función de Retención automática
11. Voltios de CA
12. Indicador de polaridad
13. Indicador de pila baja



Símbolos en la unidad

- Advertencia — Lea el manual de instrucciones
- Peligro de electrocución
- Doble forro aislante

Cómo utilizar las distintas funciones

- **EF** Oprima y mantenga este botón para detectar el campo eléctrico alrededor de los conductores que conducen corriente. El LED EF parpadeará una vez, y el emisor de tono audible emitirá un sonido corto. La intensidad de la señal se indica por medio del tono y el parpadeo del LED EF. Para el modelo GT-95, la intensidad de la señal también se muestra como una serie de guiones en la pantalla.
 - Utilice la antena integrada del verificador (consulte la sección “Identificación” en la página anterior) a fin de rastrear circuitos activados o localizar un punto de rotura en un alambre.
 - Para obtener una mayor precisión, por ejemplo para distinguir entre alambres conectados a tierra y alambres portadores de corriente, conecte un cable de prueba a la terminal de entrada + y utilícelo como una sonda.
- **Retención automática** Esta función se activa automáticamente cuando se retira el verificador después de realizar una lectura de tensión. Los diodos indicadores de luz (LED) parpadean durante 10 segundos indicando el último valor medido. La pantalla de cristal líquido (LCD) de la unidad GT-95 retiene el último valor medido y muestra el ícono .
- **Advertencia de sobretensión** El LED 1000V CA/380V CC parpadea si se excede estos niveles. La pantalla de la unidad GT-95 muestra “OL” por encima de 1000V CA o CC.
- **Autoverificación del indicador** Conecte los dos cables de prueba entre sí para ponerlos en cortocircuito. El LED de continuidad se iluminará, y el emisor de tono audible emitirá un sonido. Con los cables de prueba aún cortocircuitados, oprima y mantenga el botón **EF**. El emisor de tono audible se desactivará. Los 13 diodos emisores de luz (LED) indicadores de tensión se iluminarán durante aproximadamente 2 a 3 segundos y luego se apagarán. En la unidad GT-95, cinco de los diodos emisores de luz (LED) cambiarán de color verde a rojo, y se podrán ver todos los dígitos y los iconos en la pantalla de cristal líquido (LCD). Al final de la prueba, el LED de continuidad y el emisor de tono audible se volverán a activar.
- **Advertencia de peligro de descarga eléctrica (Modelo GT-95 solamente)** Los diodos emisores de luz (LED) de tensión aparecen de color rojo si la tensión medida es superior a 54V CC/30V CA. Por debajo de estos niveles, los diodos emisores de luz (LED) aparecen de color verde.
- **Vibrador (Modelo GT-95 solamente)** Si está habilitado, el vibrador indica que una tensión de CA mayor de aproximadamente 19 V se halla presente entre los cables de prueba. Para habilitar o deshabilitar esta función, retire los cables de prueba de cualquier fuente de tensión o continuidad. Oprima y mantenga primero el botón **GFCI** y luego el botón **EF**.
 - El vibrador permanecerá encendido hasta que se suelten los botones para confirmar que se ha habilitado la función.
 - El vibrador se encenderá momentáneamente para indicar que se ha deshabilitado la función.



GREENLEE®

Operación



ADVERTENCIA

Peligro de electrocución:

El contacto con circuitos activados podría ocasionar graves lesiones o incluso la muerte.

ATENCIÓN

Peligro de electrocución:

No cambie la función de medición mientras los cables de prueba estén conectados a un componente o circuito.

De no observarse esta advertencia pudieran sufrirse lesiones o daños a la unidad.

1. Consulte la sección “Mediciones más comunes” en relación con las instrucciones específicas para cada tipo de medición.
2. Consulte la “Tabla de verificación” en relación con las instrucciones para efectuar verificaciones.
3. Realice una Autoverificación del indicador según se describe en “Cómo utilizar las distintas funciones.” Pruebe la unidad en un circuito o componente que se sabe está funcionando perfectamente.
 - Si la unidad no funciona como debería en un circuito que se sabe está funcionando perfectamente, reemplace la pila.
 - Si sigue sin funcionar como debería, devuélvala a Greenlee a fin de que sea reparada. Consulte las instrucciones en la sección “Garantía”.
4. Anote la lectura del circuito o componente que se está verificando. Los diodos emisores de luz (LED) se iluminan según se muestra en las Tablas de los LED.

Operación (continuación)

Tabla de verificación

| Para probar/ verificar este valor: | Conecte el cable de prueba de color rojo a: | Conecte el cable de prueba de color negro a: | El verificador indicará: |
|--|---|--|---|
| Continuidad | Componente o circuito bajo prueba | Componente o circuito bajo prueba | Tono para resistencia de 0 a 50 kΩ |
| Tensión de CA | Componente o circuito bajo prueba | Componente o circuito bajo prueba | Tensión de 15 V o mayor* |
| Tensión de CC | Componente o circuito bajo prueba | Componente o circuito bajo prueba | Tensión de 4,5 V o mayor, más polaridad* |
| GFCI (Modelo GT-95 solamente) | Conductor cargado o energizado | Conexión a tierra | Consulte la sección “Mediciones más comunes” en relación con las instrucciones completas para la realización de pruebas. |

* El modelo GT-95 también muestra la tensión en la pantalla de cristal líquido (LCD).




Tabla de los LED



| LED iluminado | Indicación |
|---|--------------------------------|
| LED 1 | CC Positiva (+) de 4,5 V o más |
| LED 2 | CC Negativa (-) de 4,5 V o más |
| LED 3 | CA de 15 V o más |
| LED 4 solamente | Continuidad presente |
| Otros diodos emisores de luz (LED) de tensión | Nivel de tensión aproximado |





GREENLEE®

Mediciones más comunes



Verificación de continuidad



Medición de tensión



Detección de campo eléctrico (EF)



Consulte la sección
“Cómo utilizar las
distintas funciones”
para obtener
instrucciones
completas.

A—Sin contacto

0


B—Contacto

Mediciones más comunes

Prueba de GFCI (Modelo GT-95 solamente)

1. Consulte las instrucciones de instalación del fabricante del GFCI para verificar que el GFCI esté instalado conforme a las especificaciones del fabricante.
2. Revise para verificar que el receptáculo y todos los receptáculos conectados de manera remota estén cableados correctamente.
3. Opere el botón de prueba del GFCI instalado en el circuito. El GFCI debe dispararse.
 - Si el GFCI no se dispara, no utilice ese circuito. Consulte a un electricista.
 - Si el GFCI sí se dispara, restablézcalo. Luego conecte la unidad GT-95 en el receptáculo que se va a comprobar, según se muestra
4. Oprima el botón **GFCI** en la unidad GT-95 por un máximo de 6 segundo cuando esté verificando la condición del GFCI.
 - El LED GFCI/Continuidad se encenderá cuando se oprime el botón GFCI. Luego se apagará cuando el GFCI se dispara.
 - Si la unidad GT-95 no dispara el GFCI, probablemente:
 - existe un problema de cableado con un GFCI completamente funcional, o
 - el cableado es correcto pero el GFCI está averiado.

Consulte a un electricista para verificar las condiciones del cableado y del GFCI.



⚠ ATENCIÓN

Peligro de electrocución:

Al verificar interruptores de circuito de falla a tierra (GFCI) en sistemas bifilares (sin cable de conexión a tierra), el verificador podría indicar erróneamente que el GFCI no está funcionando de manera correcta. Si esto sucede, vuelva a verificar el funcionamiento del GFCI mediante los botones de prueba y restablecimiento. La función del botón de prueba del GFCI demostrará el funcionamiento correcto.

De no observarse esta advertencia pudieran sufrirse lesiones o daños a la unidad.